

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

07/05/2016

Report Date:

Reviewed

PPR

Mine Name: Pine Ridge Rock Products Mine Status: Permit Number: S/057/0010 Suspended Operator Name: Pine Ridge Excavation and Landscapes Inspection Date: 06/30/2016 Permit Fees: Paid Inspector(s): M. Bradley **Bond Amount:** Inspection Time: 11:45am \$68,750 Attendee(s): Iris Hennon and with Weber County Planning Weather: Cool, rainy Bond Escalation: 09/30/2019 Inspection Purpose: Follow up from enforcement 11/13/2015 Prior Inspection:

Conclusions and Recommendations

Location: SW1/4 Sec 28 & NW 1/4 Sec 33, T8N, R1E, SLBM. Wanted to inspect for regrading completeness, monitor if more mining was happening, and check revegetation. Gate was locked and could not access the site by vehicle. Weather was not amenable to going in by foot as it was raining and we did not have rain gear available. However, what could be seen is that the water truck is still on site as well as a grizzly for sizing rock. These pieces of equipment need to be removed. There is also a pile of rock remaining on the site, as was agreed to previously. There was evidence of Canadian thistle on the road into the mine, as well as surrounding areas. New signs had been posted on the gate stating that the area was now inside the Bluebell Cooperative Wildlife Management Unit through the Division of Wildlife Resources. Return again soon after coordinating access with Jed Wayment. Recommend continued monitoring when access through the gate can be gained.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
2.	Public Safety (shafts, adits, trash, signs, highwalls)		
3.	Protection of Drainages/Erosion Control		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
6.	Reclamation		
	Checked on reclamation status. Areas regraded, water truck and grizzly on sit	e. Some rock piles remain near front of ope	ration.
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
	Backfilling and regrading appear partially complete. Area in Cache County do access them.	oes not appear complete, but was not able to	directly
8.	Soils		
8. 9.	Soils Revegetation		


Inspector's Signature:

CC: Iris Hennon, Weber County Planning (ihennon@co.weber.ut.us); Chris Harrild, Cache County Planning (chris.harrild@cachecounty.org); Dan Lockwood, Pine Ridge Excavation and Landscapes (dan@pineridgeutah.com); Jed Wayment, Bluebell CWMU (wayment@allwest.net)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M057-Weber/S0570010-PineRidge/inspections/INSP-06302016.pdf



Mine: S/057/0010 Inspected: 06/30/2016



1) Sign at gated entry (by Iris Hennon)



3) Dual-locked gate




2) New sign listing site as the Bluebell Cooperative Wildlife Management Unit (CWMU) (Iris Hennon)



4) Safety warning sign on road into site







Inspected: 06/30/2016



9) Road into site with no fresh tracks



11) Piled rock near northwest corner of site



10) Regraded main excavation area with stockpiled rock at right



12) Canadian thistle on access road going in

